



UFI: AV30-X0TX-R00P-KDY3
No. 19560600, duo, 15 ml / 0.51 fl.oz.
Gefahr. Enthält: Butanon, n-Butyl-
acetat. Wiederholter Kontakt kann zu
spröder oder rissiger Haut führen.

die:master

0 µm, 15 ml

Renfert GmbH
Untere Giesswiesen 2
78247 Hilzingen/Germany
Tel. +49 7731 8208-0
www.renfert.com
Made in Germany

Renfert

217616 923F

Опасно. Содержит: Бутанон,
n-бутилацетат. Паспорт безопас-
ности на русском языке Вы найде-
те на сайте: www.renfert.com.

危險. 含: 丁酮, 乙酸正丁酯.

危険。 成分: ブタノン, n-ブチルア
セテート。

위험. 함유: 부탄온, n-부틸아세테
이트.

خطر. تحتوي على. بوتانون. ن بوتيليكيتات.

Pericol. Contine: butanonă, ace-
tat de n-butil. Expunerea repetată
poate provoca uscarea sau crăpa-
rea pielii.

Opasnost. Sadrží: butanon
n-butil-acetat. Učestalo izlaganje
može prouzročiti sušenje ili puca-
nje kože.

Danger. Contains: butanone, n-butyl acetate. Repeated exposure may cause skin dryness or cracking.

Full labeling information is provided on the outside package. Refer to the Safety Data Sheet.

Danger. Contient : butanone, acétate de n-butyle. L'exposition répétée peut provoquer dessèchement ou gerçures de la peau.

Pericolo. Contiene: butanone, acetato di n-butile. L'esposizione ripetuta può provocare secchezza e screpolature della pelle.

Peligro. Contiene: butanona, acetato de n-butilo. La exposición repetida puede provocar sequedad o formación de grietas en la piel.

Perigo. Contém: butanona, acetato de n-butilo. Pode provocar secura da pele ou fissuras, por exposição repetida.

Tehlikeler. İçerir: 2-Bütanon, Asetasidi bütilesteri. Tekrarlanan maruz kalmalarda deride kuruluğa ve çatlaklara neden olabilir.

1-50002016



No. 1956 0600
die:master duo



Renfert GmbH
Untere Giesswiesen 2
78247 Hilzingen/Germany
Tel. +49 7731 8208-0
www.renfert.com
Made in Germany

UFI: AV30-X0TX-R00P-KDY3

Gefahr. Enthält: Butanon, n-Butylacetat
Danger. Contains: butanone, n-butyl acetate

Renfert USA
3718 Illinois Avenue
St. Charles IL 60174
Toll Free (001) 800 336-7422